

Question & Answer #2



People. Partnership. Performance.

P.O. Box 1837
Tacoma, WA 98401-1837
www.portoftacoma.com

Roof Replacement at 3701 Taylor Way MASTER ID 091357 | CONTRACT NO. 070141

1. BIDDER QUESTION

Specification section 061000, 2.04 Factory Wood Treatment A.2 says "Treat wood in contact with roofing, flashing, or waterproofing." Does this mean all roof plywood must be preservative treated? The details on A6.51 only call for the cricket framing and plywood to be treated, but does not indicate the barrel roof plywood is treated.

RESPONSE

Barrel roof plywood is not required to be treated.

2. BIDDER QUESTION

Please reference spec 06 10 00-2 Part 3 –Execution 3.02 #3.

Please confirm 2x4 blocking will be required to meet the structural nailing call out of 6" OC @ panel edges.

RESPONSE

2x4 blocking will not be required at roof sheathing edges. See Addendum # 2.