



QUESTIONS & RESPONSES #02

RFP or RFQ / TITLE 071547 | Administration Building Restroom Repairs

CONTACT Heather Shadko, PROCUREMENT

EMAIL procurement@portoftacoma.com

PHONE NUMBER 253-428-8697

SUBMITTAL DUE DATE September 8, 2021 @ 11:00 AM (PST)

Q&A ISSUE DATE August 31, 2021

PROPOSER QUESTIONS	PORT RESPONSES	RFP/ RFQ Section
Can I get the make and model of the fire alarm system?	Farenhyt Series, Honeywell Model IFP-300	
Also wondering if I have a TWIC card will I be considered an escort for personnel who don't and if not what is the charge for an escort?	You can be considered an escort for non TWIC personnel, however, escorts cannot perform work. Their duty is to monitor those that do not have a TWIC. Vendors hire their own escorts, the Port is not involved in that process.	
While going through the project document pages it appears that Specs Sections 015713 & 017416 are missing according to the Table of Contents.	These sections are not required as this is an interior project. They can be eliminated from the table of contents.	