## MAINTENANCE SHED HEATING

# PROJECT NO. 101140.01 CONTRACT NO. 070735

### PORT COMMISSIONERS:

CONSTANCE T. BACON DON MEYER DONALD C. JOHNSON RICHARD P. MARZANO CLARE PETRICH


#### **PORT STAFF:**

JOHN WOLFE
Chief Executive Officer

DAKOTA CHAMBERLAIN
Director of Facilities
Development

JANE VANDENBERG, PE Director of Engineering

STANLEY RYTER, PE Project Manager



SHEET DESIGNATION	SHEET#	SHEET TITLE	REVISION
G1.1	1	COVER SHEET	
A1.1	2	SHED FLOOR PLAN	
A1.2	3	SHED ELEVATION	
M1.3	4	MECHANICAL SHED PLAN	
EO.2	5	ELECTRICAL LEGEND AND POWER RISER DIAGRAM	
E4.1	6	SHED ELECTRICAL PLAN	


#### **CONSULTANTS:**




SEATTLE 801 SECOND AVENUE, STE 700, SEATTLE, WA 99104 TEL: (206) 269 - 0104 www.cardno.com







SPECIAL INSPECTION



FILL IN GAPS BETWEEN BUILDING AND

SHED FLOOR PLAN

SCALE: 1/8" = 1'-0"

NOTE: ALL NEW INSULATION TO HAVE VINYL PROTECTIVE COVER ON INTERIOR BUILDING SIDE OF INSULATION (SIMILAR TO EXISTING)

NOTE: CONTRACTOR TO REMOVE AND PROPERLY DISPOSE OF ALL EXISTING INSULATION @ WALLS & CEILING. CONTRACTOR TO 
VERIFY & INFORM OWNER IF CURRENT INSULATION IS PLACED UNDER EXISTING ROOF STRUCTURE @ ROOF BEAMS. THE ENGINEER 

1 WILL DETERMINE IF RESULT OF INVESTIGATION POSES A STRUCTURAL INTEGRITY THREAT TO CURRENT ROOF ATTACHMENT.