

**Project/
Meeting Title:** Brown and Haley PCB Investigation

Work Order #: MID098028 **Address** _____

**Contractor/
Tenant:** Port of Tacoma

Type of Work: Sediment Sampling

Insp. Date:

6/11/2012

Sun	Mon	Tue	Wed	Thu	Fri	Sat
	X					

Weather:

Bright Sun	Clear	Overcast	Rain	Snow
------------	-------	----------	------	------

Temp: (F)

Up to 32°	32-50°	51-69°	70-85°	Over 85°
-----------	--------	--------	--------	----------

Wind:

Stagnant	Moderate	High		
----------	----------	------	--	--

Humidity:

Dry	Medium	Humid		
-----	--------	-------	--	--

A. Reason for Visit/Reported by:

City of Tacoma is planning to flush stormwater lines that may contain PCBs due to contaminated paint on the former Brown and Haley property. Reported by Anita Fichthorn and Jenn Stebbings.

B. Agency/Others present:

None.

C. Findings/Summary of activities:

The Port (Anita Fichthorn and Jenn Stebbings) took sediment samples out of manholes upstream and downstream of the Brown and Haley building to determine if contamination is present within the stormwater line. Two sediment samples were taken upstream of the Brown and Haley property and one was taken downstream (locations on attached map and labeled BH-1, BH-2 and BH-3). Anita Fichthorn submitted the samples to Analytical Resources, Inc. to test for PCBs.


D. Recommendations:

Results of the samples will be handed off to Bill Evans for follow-up.

E. Follow up/Previously reported deficiencies:

Inspector ID: _____

SIGNED: _____



Brown & Haley Drainage

<http://govME.org/map>

Property

Address

Parcel

Sewer - Storm

Storm Sewer

Storm Sewer (Private)

Storm Sewer Assets

Storm Abandon

A-Style

Catch Basin

Lamphole

Manhole

Storm Misc. Structures

Outfall

Plug

Storm Private

Pump Station

Street

Street Name

PW Off Street Line

Street Centerline

Highway

Puget Sound

Pierce County

King County

Thurston County

Aerial Photo 2009 Tacoma

3 foot pixel

City Backgrounds

Tacoma

Federal Way

Fife

Fircrest

Lakewood

