

Figure 17 – 2338 E 11<sup>th</sup> Street Building Demolition Interior Photograph



Figure 18 – 2338 E 11<sup>th</sup> Street Building Demolition Interior Photograph





Figure 19 – 2338 E 11<sup>th</sup> Street Building Demolition Interior Photograph



**Figure 20 – 2338 E 11<sup>th</sup> Street Building Demolition Interior Photograph**





**Figure 21 – 2338 E 11<sup>th</sup> Street Building Demolition Interior Photograph**



**Figure 22 – 2338 E 11<sup>th</sup> Street Building Demolition Interior Photograph**





Figure 23 – 2338 E 11<sup>th</sup> Street Building Demolition Interior Photograph




Figure 24 – 2338 E 11<sup>th</sup> Street Building Demolition Interior Photograph







Figure 25 – 2338 E 11<sup>th</sup> Street Building Demolition Interior Photograph



**Figure 26 – 2338 E 11<sup>th</sup> Street Building Demolition Interior Photograph**






Figure 27 – 2338 E 11<sup>th</sup> Street CMU Wall Demolition Plan View




Figure 28 – 2338 E 11<sup>th</sup> Street Building Demolition Plan View







Figure 29 – 2338 E 11<sup>th</sup> Street Typical Section at CrawlSpace



---

# Plan C

3502 Lincoln Avenue